MR-1 CHECK OFF LIST FOR NON-CATEGORICAL COMPANIES

CRAFT TEXTILE

27220136-outlets 1 & 2

1.	MONTH OF JANUARY 1, 2009 THRU JANUARY 31, 2009		
2.	Is Outlet # (8 digit) Correct?	N	N/A
3.	Is average Total flow-gal.day stated in space provided?	N	N/A
4.	Is max. Total flow-gal day stated in space provided?	N	N/A
5.	Is method used to calculate water stated	N	N/A
6.	Are number of working days stated? MAR 2009 Industrial Dept.	N	N/A
7.	Are there any parameters which have exceeded PVSC Local Limits?		N/A
8.	Is proper compliance/non-compliance statement provided?	N	N/A
9.	Have correct number of samples been submitted?	\mathbf{N}_{\perp}	N/A
10.	Has PHC result been listed on MR-1 report?	N ·	(N/A)
11.	Has sample number been reported in space provided?	N	N/A
12.	Have all regulated parameters been listed on MR-1?	N	N/A
13.	Has sample type been stated on MR-1?	N	N/A
14.	Have all samples been taken during this reporting period?	N	N/A
15.	Has NJDEPE certified lab been used?	N	N/A
16.	Have analytical results been submitted on copies of Laboratory stationery?	N	N/A
17.	Have results been written in space designated on MR-1?	N	N/A
18.	Is correct method used to preserve samples stated on MR-1?	N	N/A
19.	Has MR-1 been signed by authorized representative?	N	N/A
20.	Has information been submitted on proper MR-1 form?	N	N/A
21.	Remove Arsenic from report if sampling not required Y	N	N/A

MR-1 CHECK OFF LIST FOR NON-CATEGORICAL COMPANIES

Clair Textile	2722013		
First Reviewer: comments on d	leficiencies comput	et e	
Date Reviewed 3/12/09	Date sent to user		<u>. </u>
Date due back	Reviewer e g	I.m·	
Second review comments on de	eficiencies		
		.	
-			
Date Reviewed	Date sent to u	user	
Date due back	Reviewer		 . У
Date	Reviewer		

2 2009



PRETREATMENT MONITORING REPORT

NAME:

Craft Textile Printing Co., Inc.

MAILING ADDRESS:

P.O. Box 2761, Paterson, NJ 07509-2761 44 Beech Street, Paterson, NJ 07501

FACILITY LOCATION: 4 Category & Subpart: 9999

OUTLET # 1

Contact Official: H.R. Casparian

Telephone # 973-278-3818

New Customer ID/Outlet ID: 27220136-1

Old Outlet Designation: 27400061

MONITORING PERIOD

 START
 END

 1/1/2009
 1/31/2009

 m/d/yr
 m/d/yr

Regulated Flow(gal/day)
Total Flow (gal/day)

Average Maximum

N/A

FEB

35232

38755

Method Used:


Gallons in less 5% evap. divided by production days in month (11)

Production Rate:

N/A

<u>Parameter</u>	(0 /	Mass	or Concentra	ation	# of Samples	Sample Type
	\ //	Mon Avg	<u>Maximum</u>	!Jnits	- Later	Comp/Grab
Zinc	Sample Measurement	0.0448		mg/l	1	Comp
	Permit Requirement	1.67	,	mg/l		
Copper	Sample Measurement	0.00664		mg/l	1	Comp
	Permit Requirement	.092/3.02		mg/l		
Aw.	Sample Measurement					7
	Permit Requirement					
	Sample Measurement					
	Permit Requirement			2		
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement	123	156			
	Permit Requirement		60			
	Sample Measurement	/0°/ 2	6			202
	Permit Requirement	8			41771	1110162
	Sample Measurement	60/	70		10.	A 6
	Permit Requirement	D MADES	(5 009)		000	
	Sample Measurement	ust In	out A		/ Vir	
	Permit Requirement	indictris	Den 3		MAF	2009
	Sample Measurement	14	00		12	
	Permit Requirement	165	70181		A FRANCE	"input
	Sample Measurement	-0100	160		niun	atusi nehr
	Permit Requirement				120	200
	Sample Measurement				S. 8.	87179
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					

PVSC Form MR-1 Rev: 4 6/87 P1



Certification of Non-Use if applicable (use additional sheets) N/A

Compliance or non-compliance statement with compliance schedule for every parameter used:

< Local Limits: ZN , CU

> Local Limits:

N/A

< Threshold Values ZN , CU

> Threshold Values:

N/A

Craft Textile Printing Co., Inc., is in compliance with local limits.

Explain "Method for preserving samples:

Refrigerator until end of pumping, then nitric acid as a preservative to a pH less than 2.

I certify under penalty of law that this document and attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or the persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

403.6(a)(2)(ii) revised by 53 FR 40610. October 17, 1988

Signature of Principal

executive or authorized agent

H.R. Casparian-President
Name-Title
1/30/2009
Date

PVSC Form MR-1 Rev: 5 3/91 P2

PRETREATMENT MONITORING REPORT

NAME:

Craft Textile Printing Co., Inc.

MAILING ADDRESS:

P.O. Box 2761, Paterson, NJ 07509-2761

FACILITY LOCATION:

44 Beech Street, Paterson, NJ 07501

Category & Subpart: 9999

OUTLET #2

Contact Official: H.R. Casparian

Telephone # 973-278-3818

New Customer ID/Outlet ID: 27220136-2

Old Outlet Designation: 27400062

MONITORING PERIOD

Regulated Flow(gal/day)

Average Maximum N/A

START **END** 1/1/2009 1/31/2009 m/d/yr m/d/yr

Total Flow (gal/day)

16635

18299

Method Used:

Gallons in less 5% evap. divided by production days in month (9)

Production Rate:

N/A

<u>Parameter</u>		Mass	or Concent	<u>ration</u>	# of Samples	Sample Type
		Mon Avg	<u>Maximum</u>	<u>Units</u>		Comp/Grab
Zinc	Sample Measurement	Mon Avg 0.0279		mg/l	1	Comp
	Permit Requirement	1.67		mg/l		
Copper	Sample Measurement	0.025		mg/l	1	Comp
	Permit Requirement	.092/3.02		mg/l		
* DROP BOX *	Sample Measurement			1-3		
n pox k	Permit Requirement					1213147
	Sample Measurement				/,0	Mary A
	Permit Requirement				10	T
	Sample Measurement				107	
	Permit Requirement				0	
	Sample Measurement				10	MAR 20
	Permit Requirement				/63	2nd Inpr Industrial
	Sample Measurement				6	Industrial
	Permit Requirement				11	10
	Sample Measurement					6.05 WALL
	Permit Requirement			1230		0000
	Sample Measurement		631	56	1	
	Permit Requirement		(20)2	*	6	
	Sample Measurement		(e. V.		9	
	Permit Requirement		1.		03	
	Sample Measurement		(8)	\$2009	N	
	Permit Requirement		100	10.	\tag{2}	
	Sample Measurement	-	\alpha indi	stroi Do	30/	
	Permit Requirement		18	Debt.	634	
	Sample Measurement		1,00) 1/9		
	Permit Requirement			050121		
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement			8 5		

PVSC Form MR-1 Rev: 4 6/87 P1

Certification of Non-Use if applicable (use additional sheets) N/A

Compliance or non-compliance statement with compliance schedule for every parameter used:

< Local Limits:

ZN, CU

> Local Limits:

N/A

< Threshold Values ZN , CU

> Threshold Values:

N/A

Craft Textile Printing Co., Inc., is in compliance with local limits.

Explain "Method for preserving samples:

Refrigerator until end of pumping, then nitric acid as a preservative to a pH less than 2.

I certify under penalty of law that this document and attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or the persons directly responsible for gathering the information, the information submitted is. to the best of my knowledge and belief, true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

403.6(a)(2)(ii) revised by 53 FR 40610. October 17, 1988

Signature of Principal

executive or authorized agent

H.R. Casparian-President Name-Title 1/30/2009 Date

PVSC Form MR-1 Rev: 5 3/91 P2



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908-789-8900 Fax: 908-789-8922

Report of Analysis

Client:

Project:

Craft Textile Printing

Permit Renewal

Client Sample ID: OUTLET1

Lab Sample ID:

A1036-01

Date Collected: Date Received:

1/6/2009 1/6/2009

SDG No.:

A1036

Matrix:

WATER

% Solids:

0.00

kernen er		CONTRACTOR OF THE PROPERTY OF	TARING THE STREET OF THE STREE	SHIPP THE	20.1	Dilution Date Prep	Date Anal.	Method
CAS No.	Analyte	Conc.	Qualifier	Units	DL	Dilution Date (Tep		
7440-50-8 7440-66-6	Copper Zinc	6.640 44.8	J	ug/L ug/L	2.400 4.800	- (0.0000	1101200	EPA 200.7 ICP 4 EPA 200.7 ICP 4
Comments:				. 141 \$			and the second second second second	Seguit of James War will be really

U = Not Detected

DL = Method Detection Limit or Instrument Detection Limit

J = Estimated Value

B = Analyte Found In Associated Method Blank

N = Spiked sample recovery not within control limits 6

284 Sheffield Street, Mountainside, NJ 07092 Phone: 908-789-8900 Fax: 908-789-8922

Report of Analysis

Client:

Craft Textile Printing

Project:

Permit Renewal

Client Sample ID: OUTLET2

Lab Sample ID:

A1036-02

Date Collected:

1/6/2009

Date Received:

1/6/2009

SDG No.:

A1036

Matrix:

WATER

% Solids:

0.00

	A In-40	Conc.	Oualifier	Units	DL	Dilution	Date Prep	Date Anal.	Method
7440-50-8 7440-66-6	Copper Zinc	25.0 27.9		ug/L ug/L	2.400 4.800		1/8/2009 1/8/2009	11 0	EPA 200.7 ICP 4 EPA 200.7 ICP 4
Comments:									

U = Not Detected

DL = Method Detection Limit or Instrument Detection Limit

J = Estimated Value

B = Analyte Found In Associated Method Blank

N = Spiked sample recovery not within control limits 7

RAFT TEXTILE PRINTING GO, INC. PROJECT NA STATE:NJ ZIP. DASOG PROJECT NG CASCAGALA STATE:NJ ZIP. DASOG G-mall: G-mall: DATA TURNAROUND INFORMATION DAYS: CI RESULTS	001			**
PROJECT NO PROJECT MA e-mail: PHONE: In RESULTS		BILL TO:	d	PO#:
STATE:NJ ZIP: 07809 - PROJECT MANAL FAX: Q73-523-8677 PHONE: DINFORMATION DAYS: DIRESULTS		ADDRESS:		
FAR. 673-523-8677 PHONE: UND INFORMATION DAYS: CI RESULTS		GTY:	STATE:	ZIP:
LIND INFORMATION DAYS. CI RESULTS	Î	ATTENTION:	PHONE:	
DATA TUHNAHOUND INFORMATION DAYS DAYS THESUITS	FAX: DATA DELIVERABLE INFORMATION			
	J USEPA CLP J New York State ASP "B" J New York State ASP "A"			
DD: CD New Jersey CLP CD New Jersey CLP CD EDD FORMAT STANDARD TURNAROUND TIME IS 10 BUSINESS DAYS	1 Other 1 2	3 4 5 6	7 8 9	COMMENTS
CHEMTECH PROJECT SAMPLE TYPE SAMPLE S	E SAMPLE E COLLECTION E DATE TIME 2 1 2	3 4	8 2	A-HCI B-HNO, C-HSO, D-NaOH E-ICE F-Other
OUTLET #1	X X / 2 WY 0) 50/9/1			
Outlet #2	1/1/09 10AM PXX		•	
	COURIER DELIVERY	SESSION INCLUDING COL	URIER DELIVERY	
	Comments:	pt: CV Compliant Conal 4 oz jar for percent solio] -	Cooler Temp. 4°5 C
1987. T. 16/09 3 CHRISTOPHER CKER	Page / of /	SHIPPED VIA: CLIENT: [] HA CHEMTECH: [☐ HANDDELIVERED ☐ OVERNIGHT 34: IDPICKED UP ☐ OVERNIGHT	NIGHT Shippant Complete:



LING ADDRESS:___.

NON USE CERTIFICATION MONITORING REPORT LOCAL LIMITS AE CRAFT TEXTILE

LITYLO	CATION:				
EGORY	& SUBPART	PERMIT #)[III FT #·	2722000
TACTOF	FICIAL:				
/e been a	authorized to cenify n	Onelise for the fall	and the same of th		<u>.</u>
nic	Lead	dir-dae tot tite tott	owing heavy me	tals:	
		\(\sum_{\text{inc}} \)		Sampi)	EDATE
nium	Mercury	*		DAY	
mium _	Molybdenum _		*		
er	Nickel			06	09
METER	N. C.		CONCENTRATION		SAMPLE TYPE
		RESULT	THRESHOLD VALUE EXCEEDED	UNITS	COMP/GRAB
*	Sample Measurement	0.025	YES OR NO	/1	
COPPER	Threshold Value	0.092	n	mg/1	Comp.
	Sample Measurement	1.			
	Threshold Value	\	36.		-
	Sample Measurement				,
	Threshold Value				-
	Sample Measurement	/3	314.151677 1870		-Ma/s
•	Threshold Value	120	100		
]	Sample Measurement	60	-(00 N	(4-12	2
	Threshold Value		MAR SOUS	000	1567
	Sample Measurement	12	And the same	A	8
	Threshold Value	16	1 1000	V40 0	3
	Sample Measurement		15050ga0.	1st Input	NO NO
	Threshold Value			Cc2 Dept	73
	Sample Measurement			18 19 19 50 ST	N 3 CM
	Threshold Value			10000	
	Sample Measurement .				
	Threshold Value				